

Manual, Assembly instruction: Brodit 216359

With sliding power block and MultiMoveClip. 12/24V

1.)



2.)



3.)



4.)



Please read all of the instructions and look at the pictures before attaching the product.

1. Attach the mount onto the device: Place the sliding charging block onto the mount and screw it into place with the enclosed screws. Press the angled edge of the mount into the gap in the device. Place the enclosed screw in the hole and screw it into place with the enclosed tool.

2. Place the mount onto the device so the holes match. Screw the four enclosed screws in place shown in the picture.

3. Put the device into place: Hold the device on the right side of the mount. Slide it leftwards onto the mount so it snaps into place. Remove the device: Press forward on the release lever and slide the device rightwards away from the mount.

4. The product is in place.