

Manual, Assembly instruction: Brodit 216456

USB-C 3.1 holder for device with Zebra original Rugged Boot. With AMPS, VESA 75 holes.

1.)



2.)



3.)



4.)



Please read all of the instructions and look at the pictures before attaching the holder.

1. Place the holder onto the desired position and screw into place with the enclosed screws.
2. Slide the device sideways carefully into the holder. Press the spring stud locking downward to lock.
3. Press the spring stud locking upward to unlock. Slide the device sideways out of the holder.
4. The holder is in place. Switch between portrait and landscape mode by turning the holder into desired position.