

Manual, Assembly instruction: Brodit 217052

L-Bracket for Zebra Machine Vision.



Please read all of the instructions and look at the pictures before attaching the mount. The pictures show examples of how an assembly can be done. The device can be placed in any direction provided the threaded holes match the holes in the mount.

1. Place the Pedestal top mount so that the holes on the mount line up. Secure with the included screws.
2. Use the small screws with washers to mount the unit to the mount.
3. Screw back the top of the Pedestal mount.
4. The product is in place