


Manual, Assembly instruction: Brodit 852128

Center mount

1.)



1. Hook lower gap over panel at pos.

2.

2. Hook upper gap over edge at pos. 1.