

Manual, Assembly instruction: Brodit 215806

With MultiMoveClip.

1.)



2.)



3.)



4.)



Please read all of the instructions and look at the pictures before attaching the holder.

1. Remove battery from printer. Insert swivel ball into attachment port at bottom of battery compartment.
2. Swivel the plate down temporarily and put battery back into place to secure swivel ball.
3. Swivel the plate into place to cover the battery and secure using the enclosed screws.
4. The holder is in place.