

Manual, Assembly instruction: Brodit 215842

With MultiMoveClip and 2" Pedestal Mount.

1.)



Please read all of the instructions and look at the pictures before attaching the holder.

1. Attach the Quick Release Dock to the mounting plate using the enclosed self-tapping screws. Remove battery from printer. Insert swivel ball into attachment port at bottom of battery compartment.
2. Swivel the plate down temporarily and put battery back into place to secure swivel ball. Swivel the plate into place to cover the battery and secure using the enclosed screws.
3. Attach the MultiMoveClip to the pedestal using the enclosed hardware. Insert printer with attached plate into MultiMoveClip. Press release tab and slide printer out to remove.
4. The device is in place.